

PORSF
11.3.31.1.1 v31
COR



December 8, 2000

Mr. Rod Struck
Oregon Department of Environmental Quality
Voluntary Cleanup Program
2020 SW Fourth Avenue, Suite 400
Portland, Oregon 97201-4987

**Re: Marine Terminal 1 South Site
RI Data Package Report**

Dear Mr. Struck:

The Port of Portland (Port) has compiled sampling data from the remedial investigation (RI) of soil and groundwater at the Port's Marine Terminal 1 (T1) South site. The attached T1 Data Package, dated November 16, 2000, documents all the sampling results from Phases 1 and 2 of the RI and is provided to the Oregon Department of Environmental Quality for review. These sampling results are being used to determine the scope of the proposed removal action and will be incorporated into the T1 RI report.

Please contact me at (503) 944-7533 with any questions.

Sincerely,

Joe Mollusky
Environmental Project Manager
Property and Development Services

Attachments (2)

cc: Peggy Krause, Port (w/o attachment)
Nancy Murray, Port (w/o attachment)
Guy Tanz, Hahn and Associates (w/o attachment)

